

SERVICE REPORT

, ,		A N	New Genera	tion of Power					S	Submit	
JOB STATU	S: Complete	,	SALES ORDER #	#: 237	78SE)					
CUSTOMER NAME: MDA Lending Solutions				PROJECT NAME	1E: Quarterly Inspection						
DATE OF SERVICE: 03/06/15				_	ESS: 1421 wells Branch Parkway						
TYPE OF SERVICE CALL: Inspection - Quarterly				_	Pflugerville, Tx 787660						
THE OF SERVICE CALE. MISPOSION Quartery											
				UNIT	Elliot 150KW						
LUBRICATION CHECKS: IGNITION SYSTEM CH				CHECKS:	EXHAU	CHAUST SYSTEM CHECKS:					
_evel Full		Plugs				Leaks None Found					
Leak None For	und	Wires	N/A		Turbo Charger Good						
Filter Good		Сар	N/A		Condensation	·					
Condition Good		Points	N/A		Wet Stack	None Present					
Sample Taken: Yes No		Rotor	N/A		Flex Pipe	Good					
Changed Oil: Yes • No		Fuel Injection	n <u>Good</u>		Rain Cap	Good					
COOLING SYSTEM	I / RI OCK	R/	ATTERY CHEC	.kc.	GA	UGE R	FADIN	iec			
HEATER CHECKS:		Float Charge		жэ.	AC Voltage AB	479	BC	478	CA	479	
Filters N / A		A/T-Engine			AC VOITAGE AD	277	- BN	275	CN	276	
Heater Good		Water Level			A*	-	– B*	-	C*		
Leaks None For	und	Load Test	9.8		Frequency	60					
Level Good		Spec Gravity		,	Oil Pressure	46					
Hoses See Comments		Terminals	Ok		Engine Temp	172				_	
Belts Good					Hour Meter	355.	.4				
DCA Good	•	AIR FILTER									
Sample Taken: Yes No		Condition Clean			PARTS USED						
					DESCRIF	PTION		PA	RT#	QTY	
			FINAL V	EW							
FUEL SYSTEM CHECKS:		Generator Er	nclosure <u>Go</u>	od							
Filter Good		AGS Sticker Good		od							
Fuel Seperator N / A		System in Au	ito <u>Ye</u>	s							
Lines Good		Circuit Breaker Closed Yes		S							
Solenoid Good		ATS in Auto	Ye	S							
Level 3/4		ATS Enclosure	e Secured <u>Ye</u>	S							
Pump Good		Maintenance	Reset N	/A							
Basin Good											
CVCTENAC ODI	EDATION CUECUC									-	
	ERATION CHECKS:										
Generator Run w/o Lo											
Fransfer Switch w/o L										+-	
Fransfer Switch w/ Lo										+-	
		<u>-</u>								+-	
										_	
Generator Operation	<u> </u>									Щ	
COMMENTS:				d at this time.							
Arrived on site and p	performed quarterly i	nspection. No p	roblem found	d at this time.							
				4							

Customer / Authorized Signature

AGS Technician - Billy Fansler