

Great Lakes Industrial Diesel

2-23-21

CSDG: 2839

Generator Check list

Inspection Description

- Yes No NA Check coolant level and record freeze protection: Coolant good to -25 deg F
- Yes No NA Visual inspection of radiator: No visible issues or performance issues
- Yes No NA Visual inspection of radiator hoses: No visible issues
- Yes No NA Check condition of coolant hoses: No visible issues
- Yes No NA Check condition of fuel hoses: No visible issues
- Yes No NA Check condition of engine belts: Good working condition
- Yes No NA Batteries and QTY: 1 Group 27 good battery
- Yes No NA Battery install date if applicable: No install date marked
- Yes No NA Genset has battery charger: Installed on side of doghouse
- Yes No NA Genset has coolant heater: Coolant heater is on genset
- Yes No NA Check engine oil level: Oil level full
- Yes No NA Engine oil filters last changed date and HRS: Fresh engine oil and filter @ 222HRS
- Yes No NA Inspect exhaust system for cracks / leaks: No issues with exhaust system
- Yes No NA Check rain cap for proper operation: Rain cap working as designed
- Yes No NA Generator end is 12 lead reconnectable: Unit is connected to 208 VAC
- Yes No NA Generator end has PMG permanent magnet generator: Generator has a PMG