

Great Lakes Industrial Diesel

3-1-21

CSDG: 2860

Generator Check list

Inspection Description

- Yes No NA Check coolant level and record freeze protection: **New 50/50 mixed coolant**
- Yes No NA Visual inspection of radiator: **No visible issues or performance issues**
- Yes No NA Visual inspection of radiator hoses: **No visible issues**
- Yes No NA Check condition of coolant hoses: **No visible issues**
- Yes No NA Check condition of fuel hoses: **No visible issues**
- Yes No NA Check condition of engine belts: **Good working condition**
- Yes No NA Batteries and QTY: **No batteries on the unit used test batteries to run**
- Yes No NA Battery install date if applicable: **No install date marked**
- Yes No NA Genset has battery charger: **Battery charger mounted on doghouse**
- Yes No NA Genset has coolant heater: **120VAC coolant heater is on genset**
- Yes No NA Check engine oil level: **Oil level full**
- Yes No NA Engine oil filters last changed date and HRS: **Last service was 2-24-21/ 126 HRS**
- Yes No NA Inspect exhaust system for cracks / leaks: **No issues with exhaust system**
- Yes No NA Check rain cap for proper operation: **No exhaust system elbow off turbo is covered with a plate**
- Yes No NA Generator end is 12 lead reconnectable: **Unit is connected to 480 VAC**
- Yes No NA Generator end has PMG permanent magnet generator: **No PMG**