

Great Lakes Industrial Diesel

3-10-21

CSDG: 2867

Generator Check list

Inspection Description

- Yes No NA Check coolant level and record freeze protection: Full good to -25 deg. F.
- Yes No NA Visual inspection of radiator: No visible issues or performance issues
- Yes No NA Visual inspection of radiator hoses: No visible issues
- Yes No NA Check condition of coolant hoses: No visible issues
- Yes No NA Check condition of fuel hoses: No visible issues
- Yes No NA Check condition of engine belts: Good working condition
- Yes No NA Batteries and QTY:
- Yes No NA Battery install date if applicable:
- Yes No NA Genset has battery charger:
- Yes No NA Genset has coolant heater: 2-240/480 Jacket water heaters on engine
- Yes No NA Check engine oil level: Oil level full
- Yes No NA Engine oil filters last changed date and HRS: Last changed 5-2-2020 @ 378HRS
- Yes No NA Inspect exhaust system for cracks / leaks: No issues with exhaust system
- Yes No NA Check rain cap for proper operation: Exhaust is covered with a plate
- Yes No NA Generator end is 12 lead reconnectable: 12 lead wired 480VAC
- Yes No NA Generator end has PMG permanent magnet generator: Unit has a PMG