

Great Lakes Industrial Diesel

3-9-21

CSDG: 2879

Generator Check list

Inspection Description

- Yes No NA Check coolant level and record freeze protection: New coolant good to -34 deg F
- Yes No NA Visual inspection of radiator: No visible issues or performance issues
- Yes No NA Visual inspection of radiator hoses: No visible issues
- Yes No NA Check condition of coolant hoses: No visible issues
- Yes No NA Check condition of fuel hoses: No visible issues
- Yes No NA Check condition of engine belts: Good working condition
- Yes No NA Batteries and QTY: No batteries or battery cables
- Yes No NA Battery install date if applicable:
- Yes No NA Genset has battery charger: No charger
- Yes No NA Genset has coolant heater: Coolant heater is on genset
- Yes No NA Check engine oil level: Oil level full
- Yes No NA Engine oil filters last changed date and HRS: Fresh oil change and fuel filter change 3-9-21
- Yes No NA Inspect exhaust system for cracks / leaks: No issues with exhaust system
- Yes No NA Check rain cap for proper operation: No rain cap exhaust covered with plate
- Yes No NA Generator end is 12 lead reconnectable: Unit is connected to 480 VAC
- Yes No NA Generator end has PMG permanent magnet generator: Unit has a PMG