



Customer: Central States Diesel Generators STK#3121  
 Address: 2001 S Prairie Ave.  
 City/ State/ Zip Waukesha, WI 53189  
 Contact: Patrick Paden  
 Phone: 262-955-7655

R#: 12014  
 Test Date 10-4-21

Engine Make/ Model: IVECO F2CE9685A  
 Engine Spec/ Serial: E001-014758  
 Unit Make/ Model: Gillette Generators SPID-2500-3-2S  
 Unit Spec/ Serial: IE-19-301

Voltage: 120/208  
 Amperage: 694  
 Kilowatts: 250  
 Power Factor 1.0

	5 Min.	15 Min.	30 Min.	45 Min.	1 Hour	Cool Down
Eng Hours	0.4	0.6	0.9	.1.1	1.4	1.5
Hertz/Cycles	60	60	60	60	60	60
Voltage PH1	208	208	208	208	208	208
PH1 to N	208	208	209	208	208	208
PH2 to N	208	208	208	208	208	208
Amperage PH1	695	694	694	694	695	0
PH2	694	694	694	695	694	0
PH3	694	694	695	695	694	0
Kilowatts	250	250	250	250	250	0
Oil Pressure	73	72	72	72	72	74
Oil Temperature						
Coolant Temperature	180°F	180°F	180°F	180°F	180°F	178°F
Man Vac./Press. L/B						
Man Vac./Press. R/B						
L/B Exhaust Temp						
R/B Exhaust Temp						
Exhaust Temperature						
DC Voltage	14	14	14	14	14	14
Natural Gas Pressure						
Diesel Fuel Level						
Room Temperature						
Ambient Temperature	66°F	66°F	67°F	67°F	67°F	67°F

Technician Signature: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

## Charles Equipment

10-4-21

CSDG # 3121

### Generator Check list

#### Inspection Description

- Yes  No  NA Check coolant level and record freeze protection: Level Good -30F
- Yes  No  NA Visual inspection of radiator: No visible issues or performance issues
- Yes  No  NA Visual inspection of radiator hoses: No visible issues
- Yes  No  NA Check condition of coolant hoses: No visible issues
- Yes  No  NA Check condition of fuel hoses: No visible issues
- Yes  No  NA Check condition of engine belts: Good Condition
- Yes  No  NA Batteries and QTY: (2) P/N 24S 12VDC
- Yes  No  NA Battery install date if applicable: Not Tagged
- Yes  No  NA Genset has battery charger: 120VAC input/Dual 12VDC output 10A
- Yes  No  NA Genset has coolant heater: 240V 1PH / 2000Watt
- Yes  No  NA Check engine oil level: Oil level is full/Appearance Excellent
- Yes  No  NA Engine oil filters last changed date and HRS: 10-4-2021
- Yes  No  NA Inspect exhaust system for cracks / leaks: No issues with exhaust system
- Yes  No  NA Check rain cap for proper operation: OK
- Yes  No  NA Generator end is 12 lead reconnectable: OK
- Yes  No  NA Generator end has PMG permanent magnet generator: Yes