



Customer: Central States Diesel Generators STK# 3233
 Address: 2001 S Prairie Ave.
 City/ State/ Zip Waukesha, WI 53189
 Contact: Patrick Paden
 Phone: 262-955-7655

R#: 12421
 Test Date 12-20-21

Engine Make/ Model: mitsubishi 2.5L
 Engine Spec/ Serial: _____
 Unit Make/ Model: GENERAC G0070900
 Unit Spec/ Serial: 3000968502

Voltage: 120/240 1PH
 Amperage: 84
 Kilowatts: 20
 Power Factor 1.0

	5 Min.	15 Min.	30 Min.	45 Min.	1 Hour	Cool Down
Eng Hours	149.7	150	150.2	150.5	150.7	150.8
Hertz/Cycles	60	60	60	60	60	60
Voltage PH1 to PH2	240	241	241	241	241	241
PH1 to N	120	120	120	121	120	121
PH2 to N	121	121	120	121	121	121
Amperage PH1	84	84	83	84	83	0
PH2	83	83	84	83	84	0
PH3	0	0	0	0	0	0
Kilowatts	20	20	20	20	20	0
Oil Pressure	34	33	33	33	33	36
Oil Temperature						
Coolant Temperature	176°F	176°F	176°F	176°F	176°F	175°F
Man Vac./Press. L/B						
Man Vac./Press. R/B						
L/B Exhaust Temp						
R/B Exhaust Temp						
Exhaust Temperature						
DC Voltage	14.7	14.7	14.7	14.7	14.7	14.7
Natural Gas Pressure						
Diesel Fuel Level						
Room Temperature						
Ambient Temperature	33°F	33°F	34°F	34°F	34°F	34°F

Technician Signature: _____

Customer Signature: _____

Charles Equipment

12-20-21

CSDG # 3233

Generator Check list

Inspection Description

- Yes No NA Check coolant level and record freeze protection: Level Good Freeze@ -35F
- Yes No NA Visual inspection of radiator: Okay
- Yes No NA Visual inspection of radiator hoses: No visible issues
- Yes No NA Check condition of coolant hoses: Okay
- Yes No NA Check condition of fuel hoses: No visible issues
- Yes No NA Check condition of engine belts: Good Condition
- Yes No NA Batteries and QTY: (1) Interstate M-35 RC80 450CCA
- Yes No NA Battery install date if applicable: 7/2021
- Yes No NA Genset has battery charger: Generac 0F1740C 120VAC input/12VDC 10A output
- Yes No NA Genset has coolant heater: QTY. (1) 120V 1800W HOTSTART
- Yes No NA Check engine oil level: Oil level is full
- Yes No NA Engine oil filters last changed date and HRS: NOT DATED
- Yes No NA Inspect exhaust system for cracks / leaks: Okay
- Yes No NA Check rain cap for proper operation: Not Present
- Yes No NA Generator end is 12 lead reconnectable: NO
- Yes No NA Generator end has PMG permanent magnet generator: No