



Customer: Central States Diesel Generators STK#3241  
 Address: 2001 S Prairie Ave.  
 City/ State/ Zip Waukesha, WI 53189  
 Contact: Patrick Paden  
 Phone: 262-955-7655

R#: 12749  
 Test Date 2-2-22

Engine Make/ Model: ISUZU 4LE1NYGV04 KV-4LE1  
 Engine Spec/ Serial: 160909023 897369555  
 Unit Make/ Model: DG04RZ055V1M00001  
 Unit Spec/ Serial: 95160600157

Voltage: 120/208  
 Amperage: 55  
 Kilowatts: 20  
 Power Factor 1.0

	5 Min.	15 Min.	30 Min.	45 Min.	1 Hour	Cool Down
Eng Hours	58	58	58	58	59	59
Hertz/Cycles	61	61	61	61	61	61
Voltage PH1 to PH2	209	209	209	209	210	209
PH2 to PH3	209	209	209	209	210	209
PH1 to PH3	209	209	209	209	209	209
Amperage PH1	53	52	53	53	52	0
PH2	52	53	52	52	53	0
PH3	53	53	52	52	53	0
Kilowatts	19	19	19	19	19	0
Oil Pressure	67	66	66	66	66	68
Oil Temperature						
Coolant Temperature	136°F	136°F	136°F	137°F	137°F	135°F
Man Vac./Press. L/B						
Man Vac./Press. R/B						
L/B Exhaust Temp						
R/B Exhaust Temp						
Exhaust Temperature						
DC Voltage	14.2	14.2	14.2	14.2	14.2	14.2
Natural Gas Pressure						
Diesel Fuel Level						
Room Temperature						
Ambient Temperature	9023 8973	16°F	16°F	16°F	16°F	16°F

Technician Signature: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

## Charles Equipment

2-2-22

CSDG # 3241

### Generator Check list

#### Inspection Description

- Yes  No  NA Check coolant level and record freeze protection: Level Good Freeze@ -35F
- Yes  No  NA Visual inspection of radiator: No visible issues
- Yes  No  NA Visual inspection of radiator hoses: No visible issues
- Yes  No  NA Check condition of coolant hoses: No visible issues
- Yes  No  NA Check condition of fuel hoses: No visible issues
- Yes  No  NA Check condition of engine belts: No Visible issues
- Yes  No  NA Batteries and QTY: Qty. (1) 12V Powerfast PF-31P-7
- Yes  No  NA Battery install date if applicable: 6/21
- Yes  No  NA Genset has battery charger: MTU 79100 120VAC input 12VDC/6A output
- Yes  No  NA Genset has coolant heater: QTY. (1) 120VAC/500 Watt
- Yes  No  NA Check engine oil level: Oil level is full
- Yes  No  NA Engine oil filters last changed date and HRS: NOT MARKED
- Yes  No  NA Inspect exhaust system for cracks / leaks: No visible issues
- Yes  No  NA Check rain cap for proper operation: No visible issues
- Yes  No  NA Generator end is 12 lead reconnectable: YES