



Customer: Central States Diesel Generators STK#3537  
 Address: 2001 S. Prairie Ave.  
 City/ State/ Zip Waukesha, WI 53189  
 Contact: Patrick Paden  
 Phone: 847.997.8090

R#: 12967  
 Test Date 4-19-22

Engine Make/ Model: Cummins 6CTA8.3  
 Engine Spec/ Serial: 21263117  
 Unit Make/ Model: Cummins 200DGFC  
 Unit Spec/ Serial: Spec.- 89357A S/N - I970648512

Voltage: 277/480  
 Amperage: 241  
 Kilowatts: 200  
 Power Factor 0.8

	5 Min.	15 Min.	30 Min.	45 Min.	1 Hour	Cool Down
Eng Hours	467.3	467.6	467.8	468	468.3	468.4
Hertz/Cycles	60	60	60	60	60	60
Voltage PH1	482	482	481	482	481	482
PH2	481	481	480	481	481	481
PH3	481	481	481	482	481	481
Amperage PH1	240	240	240	239	240	0
PH2	239	239	240	240	240	0
PH3	239	240	239	240	240	0
Kilowatts	199	200	199	200	200	0
Oil Pressure	55	55	55	54	54	54
Oil Temperature						
Coolant Temperature	182°F	182°F	182°F	181°F	181°F	178°F
Man Vac./Press. L/B						
Man Vac./Press. R/B						
L/B Exhaust Temp						
R/B Exhaust Temp						
Exhaust Temperature						
DC Voltage	13.6	13.6	13.6	13.6	13.6	13.6
Natural Gas Pressure						
Diesel Fuel Level						
Room Temperature						
Ambient Temperature	44°F	44°F	44°F	44°F	45°F	45°F

Technician Signature: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

## Charles Equipment

4-19-22

CSDG # 3537

### Generator Check list

#### Inspection Description

- Yes  No  NA Check coolant level and record freeze protection: Level Good Freeze @ -40Deg. F
- Yes  No  NA Visual inspection of radiator: No visible issues
- Yes  No  NA Visual inspection of radiator hoses: No visible issues
- Yes  No  NA Check condition of coolant hoses: No visible issues
- Yes  No  NA Check condition of fuel hoses: No visible issues
- Yes  No  NA Check condition of engine belts: No Visible issues
- Yes  No  NA Batteries and QTY: Qty (1) Commander Series 4D
- Yes  No  NA Battery install date if applicable: 1/16/2020
- Yes  No  NA Genset has battery charger: SENS Micro Genius
- Yes  No  NA Genset has coolant heater: Kim Hotstart TPS101GT10-000 120VAC/1000W
- Yes  No  NA Check engine oil level: Oil level is full
- Yes  No  NA Engine oil filters last changed date and HRS: Not Marked
- Yes  No  NA Inspect exhaust system for cracks / leaks: No visible issues
- Yes  No  NA Check rain cap for proper operation: Okay
- Yes  No  NA Generator end is 12 lead reconnectable: YES
- Yes  No  NA Generator end has PMG permanent magnet generator: YES