





Customer:	Central States Diesel Generators STK#3853					
Address:	2001 S. Prairie Ave.					
City/ State/ Zip	Waukesha, WI 53189					
Contact:	Patrick Paden					
Phone:	847.997.8090					

**R#:** TBA **Test Date** 1-13-23

Engine Make/ Model: John Deere 4024TF281	<b>Voltage:</b> 120/240 1Ph
Engine Spec/ Serial: PE4024R101727	Amperage: 104
Unit Make/ Model: John Deere 4024TF281	Kilowatts: 25
Unit Spec/ Serial: PE4024R101727	Power Factor 1

	5 Min.	15 Min.	30 Min.	45 Min.	1 Hour	Cool Down
Eng Hours	2779.2	2779.4	2779.7	2779.9	2789.2	2780.3
Hertz/Cycles	60	60	60	60	60	60
Voltage PH1-PH2	242	242	242	242	242	241
Amperage PH1	104	104	103	104	104	0
PH2	103	104	104	103	104	0
Kilowatts	25	25	25	25	25	0
Oil Pressure	46	45	45	45	45	47
Oil Temperature						
Coolant Temperature	201°F	201°F	201°F	201°F	201°F	189°F
Man Vac./Press. L/B						
Man Vac./Press. R/B						
L/B Exhaust Temp						
R/B Exhaust Temp						
Exhaust Temperature						
DC Voltage	14.1	14.1	14.1	14.1	14.1	14.1
Natural Gas Pressure						
Diesel Fuel Level						
Room Temperature						
Ambient Temperature	28°F	28°F	28°F	28°F	27°F	27°F

Technician Signature: \_\_\_\_\_ Customer Signature: \_\_\_\_\_

### **Charles Equipment**

#### 1-13-23

# CSDG # 3853

# **Generator Check list**

#### Inspection Description

- ⊠ Yes □ No □ NA Check coolant level and record freeze protection: Level Good -35F
- ⊠ Yes □ No □ NA Visual inspection of radiator: <u>No visible issues or performance issues</u>
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Visual inspection of radiator hoses: <u>No visible issues</u>
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Check condition of coolant hoses: <u>No visible issues</u>
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Check condition of fuel hoses: <u>No visible issues</u>
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Check condition of engine belts: <u>Good Condition</u>
- Yes I No I NA Batteries and QTY: (1) NAPA 7524
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Battery install date if applicable: <u>11/22</u>
- $\Box$  Yes  $\boxtimes$  No  $\Box$  NA Genset has battery charger: <u>No</u>
- $\Box$  Yes  $\boxtimes$  No  $\Box$  NA Genset has coolant heater: <u>No</u>
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Check engine oil level: <u>Oil level is full</u>
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Engine oil filters last changed date and HRS: <u>NA</u>
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Inspect exhaust system for cracks / leaks **No issues with exhaust system**
- $\boxtimes$  Yes  $\square$  No  $\square$  NA Check rain cap for proper operation: <u>**Good**</u>
- □ Yes ⊠ No □ NA Generator end is 12 lead reconnectable: <u>No</u>
- ☑ Yes □ No □ NA Generator end has PMG permanent magnet generator: <u>Yes</u>