



01/17/24

CSDG #4146

Generator Check list

Inspection Description

- Yes No NA Check coolant level and record freeze protection: -50F
- Yes No NA Visual inspection of radiator: Good
- Yes No NA Visual inspection of radiator hoses: Good
- Yes No NA Check condition of coolant hoses: Good
- Yes No NA Check condition of fuel hoses: Acceptable
- Yes No NA Check condition of engine belts: Good
- Yes No NA Batteries and QTY: 1
- Yes No NA Battery install date if applicable: Battery looks new
- Yes No NA Genset has battery charger: No
- Yes No NA Genset has coolant heater: Yes
- Yes No NA Check engine oil level: Full
- Yes No NA Engine oil filters last changed date and HRS: No time Stamp
- Yes No NA Inspect exhaust system for cracks / leaks: 120VAC 1500W
- Yes No NA Check rain cap for proper operation:
- Yes No NA Generator end is 12 lead reconnectable:
- Yes No NA Generator end has PMG permanent magnet generator:
- Yes No NA Mechanical Engine: