



**1/16/2024**

**CSDG #4366**

### **Generator Check list**

#### Inspection Description

- Yes  No  NA Check coolant level and record freeze protection: -25F
- Yes  No  NA Visual inspection of radiator: Good
- Yes  No  NA Visual inspection of radiator hoses: Good
- Yes  No  NA Check condition of coolant hoses: Good
- Yes  No  NA Check condition of fuel hoses: Good
- Yes  No  NA Check condition of engine belts: Good
- Yes  No  NA Batteries and QTY: 2
- Yes  No  NA Battery install date if applicable: No date
- Yes  No  NA Genset has battery charger:
- Yes  No  NA Genset has coolant heater: Block heater
- Yes  No  NA Check engine oil level: Full and Clean
- Yes  No  NA Engine oil filters last changed date and HRS: 11/30/2022 HRS 407
- Yes  No  NA Inspect exhaust system for cracks / leaks:
- Yes  No  NA Check rain cap for proper operation: detached inside gen housing
- Yes  No  NA Generator end is 12 lead reconnectable:
- Yes  No  NA Generator end has PMG permanent magnet generator:
- Yes  No  NA Electronic Engine: