



02/05/2024

CSDG # 4411

Generator Check list

Inspection Description

- Yes No NA Check coolant level and record freeze protection: -25
- Yes No NA Visual inspection of radiator: Excellent
- Yes No NA Visual inspection of radiator hoses: Good
- Yes No NA Check condition of coolant hoses: Good
- Yes No NA Check condition of fuel hoses: Good
- Yes No NA Check condition of engine belts: Good
- Yes No NA Batteries and QTY: 1x, Core, C31AXHD
- Yes No NA Battery install date if applicable: 2/14/23
- Yes No NA Genset has battery charger: EnerGenius NRG22-10-RC, 120/208-240V, 6/3 Amps
- Yes No NA Genset has coolant heater: 1500W 120V
- Yes No NA Check engine oil level: Good
- Yes No NA Engine oil filters last changed date and HRS: 02/02/2024
- Yes No NA Inspect exhaust system for cracks / leaks: Good
- Yes No NA Check rain cap for proper operation: Excellent
- Yes No NA Generator end is 12 lead reconnectable:
- Yes No NA Generator end has PMG permanent magnet generator:
- Yes No NA Electronic Engine: